

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	09/22/2016 09/22/2016	Herman Phillips

LM Start		Rating **	A	Issue No.	3
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
				°	°
DWR ID	DWR_RD2068_01_f_2014_3				
Comment Code					
Inspector Comment					
RD 2068 has the O&M Manual on hand.					

No Photos

LM Start		Rating **	A	Issue No.	4
LM End		Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
				°	°
DWR ID	DWR_RD2068_01_f_2014_4				
Comment Code					
Inspector Comment					
RD 2068 crew members are trained yearly.					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

# Reclamation District No. 2068 Yolano

No Photos

Looking downstream from the landside levee slope.

RD 2068 Looking downstream from the waterside levee slope.

Page 2 of 3

**Flood Control Project Maintenance  
Levee Inspections**

## Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016

### Reclamation District No. 2068 Yolano

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Yolo Bypass	Right	5.48	09/22/2016 09/22/2016	Herman Phillips

LM Start	2.11	Rating **	M	Issue No.	11
LM End	2.46	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.378028 °	38.372862 °
				-121.693908 °	-121.693978 °
DWR ID	DWR_RD2068_01_f_2016_11				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
There are active rodents in the area, several holes were seen but no bait stations observed on the slope where rodents were noted.					

Photo 1 of 2 : FA\_2016\_RD2068\_193\_11\_20160926\_00003.jpg



RD 2068 looking downstream landside slope from levee miles 2.11 -2.46.

LM Start	<b>2.11</b>	Rating **	M	Issue No.	<b>11 (cont)</b>
LM End	<b>2.46</b>	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : FA\_2016\_RD2068\_193\_11\_20160926\_00004.jpg



RD 2068 looking downstream landside slope from levee miles 2.11-2.46.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2068 Yolano**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.22	09/22/2016 09/22/2016	Herman Phillips

LM Start	0.01	Rating **	A	Issue No.	10
LM End	2.73	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.358232°	38.392895°
				-121.740370°	-121.720985°
DWR ID	DWR_RD2068_02_f_2016_10				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
there is no unwanted vegetation along the landside levee slope 0.01-2.73. The Maintaining Agency recently mowed the site.					

No Photos

LM Start	0.01	Rating **	A	Issue No.	11
LM End	2.73	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.358232 °	38.392895 °
				-121.740370 °	-121.720985 °
DWR ID	DWR_RD2068_02_f_2016_11				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
there is no unwanted vegetation along the waterside levee slope 0.01-2.73. The Maintaining Agency recently mowed the site.					

Photo 1 of 1 : FA\_2016\_RD2068\_194\_11\_20160926\_00007.jpg



RD 2068 looking downstream from levee mile 0.01-2.73.

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance  
Levee Inspections**

**Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2016**

**Reclamation District No. 2068 Yolano**

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Back Levee	Left	3.22	09/22/2016 09/22/2016	Herman Phillips

LM Start	<b>2.73</b>	Rating **	C	Issue No.	<b>12</b>
LM End	<b>3.22</b>	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.392895°	38.398762°	
			-121.720985°	-121.715631°	
DWR ID	DWR_RD2068_02_f_2016_12				
Comment Code					
V9 : Keep the crown roadway free of vegetation.					
Inspector Comment					

No Photos

<b>* Location</b> LS : Land Side    N/A : Not Applicable WS : Water Side CR : Crown	<b>** Rating</b> A : Acceptable                      N : Not Inspected/Rated M : Minimally Acceptable        C : Corrected U : Unacceptable                  A/W : Acceptable but Monitor & Maintain	<b>+ Issue Type</b> Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---